

**HOBOKEN DIVISION
FLAGMAN AND EXTRA SERVICE REPORT
Tuesday, December 5, 2017**

O/D Time	Location	Consist	Instructions	WO #	Contact / Phone
600am (Tu-F)	Hoboken	1-Cndr	DH 607 to Broad St. Station, Newark and meet with George Harms Construction (Cont'r) for work along the ROW.	L110549	G. Petrillo 973-768-9429
600am (Tu)	Hoboken	Full Crew	NO UNIFORM. DH 607 to the MMC and report to the Yardmaster for an engine. run lite to the out of service track 3 west of Green and couple to loaded gons of ties and jimbo on the South Orange Back Lead and WAD by the M of W Supervisor.	RRZ8481	L. Green 973-418-5571
623am (Tu-F)	Hoboken	3-Cndrs	DH 211 to Park Ave., UG Br., MP 9.39 and meet with ARS Tree Trimmers (Cont'r) for work along the ROW.	L051090	S. Cruz 973-766-6281
626am (Tu)	Dover Yd.	1-Cndr	DH 6614 to the Atlantic Brick Switch, MP 22.7 and meet with ARS Tree Trimmers (Cont'r) for work along the ROW.	L051090	S. Cruz 973-766-6281
627am (Tu)	Hoboken	1-Cndr	DH X135 to the Private Crossing, Secaucus, MP 4.9 (behind the dog pound) and meet with J. Fletcher Creamer (Cont'r) for work along the ROW.	L074076	G. Petrillo 973-768-9429
739am (Tu)	Hoboken	2-Cndrs	DH 409 to Summit Station and meet with the Bridge Inspectors in the waiting room at 9:15am.	L059218	E. Bier 973-493-0088
619pm (Tu-F)	Hoboken	1-Cndr	DH 813 to Broad St. Station, Newark and meet with George Harms Construction (Cont'r) for work along the ROW.	L110549	G. Petrillo 973-768-9429

THE FOLLOWING JOB HAS BEEN REQUESTED FOR TONIGHT: Monday, December 4, 2017

O/D Time	Location	Consist	Instructions	WO #	Contact / Phone
619pm (M)	Hoboken	1-Cndr	DH 813 to Broad St. Station, Newark and meet with George Harms Construction (Cont'r) for work along the ROW.	L110508	G. Petrillo 973-768-9429
900PM (M)	Port Jervis Yd.	Full Crew	NO UNIFORM. Run 4102-4 cars-4000 from Port Jervis Yard to Hoboken. (50 MPH speed restriction on equipment) The above extra service job is "High Priority."	L050282	Hoboken Yardmaster 201-714-2938
1139PM (M)	Hoboken	Full Crew	NO UNIFORM. DH 453 to the MMC and report to the MMC Yardmaster for an engine. Run lite to the Port Morris Material Yard and P/U 3 loaded gons of ties (9404,19,22) and take them to the South Orange Back Lead and set them out. P/U 3 empty gons (9421,06,17) and take them to the MMC. The above extra service job is "High Priority."	RRZ8481	L. Green 973-418-5571
1139PM (M)	Hoboken	Full Crew	NO UNIFORM. DH 453 to the MMC and report to the Yardmaster for an engine. Run to the New Connection Switch and P/U 4 side dumps and take them to the MMC.	JLX4610	L. Green 973-418-5571

SEE PAGE TWO

PAGE TWO

THE FOLLOWING HAS BEEN AWARDED BY ADVERTISEMENT

O/D Time	Location	Consist	JOB #	Instructions	WO #	Contact / Phone
523am	Hoboken	1-Cndr	HF94	DH 871 to the Rt. 7 OH Br., MP 3.60 (ME) and meet with IEW (Cont'r) for work along the ROW.	L073896	G. Petrillo 973-768-9429
554am	Dover Yd.	1-Cndr	DF92	DH 6612 to Morris Ave., OH Br., Summit, MP 20.51 and work with IEW (Cont'r) on bridge replacement project.	RDK6000	W. Wludyka 732-803-0403
559am	Gladstone Yd.	1-Cndr	GL91	DH 408 to Lyons Station and meet Northeast Roofing (Cont'r) and WAD.	L074014	G. Petrillo 973-768-9429
605am	Hoboken	1-Cndr	HF92	DH X125 to Rutherford Station and meet Sparwick (Con't) and WAD replacing/repairing the station plaza.	NFS5000	M. Arcila 973-300-4709
615am	Gladstone Yd.	1-Cndr	GL90	Meet with Vanalt/Parsons (Cont'r) for communications work along the ROW. Note: will need to travel with the contractor to various locations.	JLX3050	R. Soto 973-919-8438
649am	Dover Yd.	1-Cndr	DF91	DH 6616 to Denville Station and meet with Vanalt/Parsons (Cont'r) for communications work along the ROW.	JLX3050	R. Soto 973-919-8438